
## nergy efficiency rating for this property

is property's current energy rating is G. It has the potential to be B.

e how to improve this property's energy performance.



e graph shows this property's current and potential energy efficiency.

operties are given a rating from A (most efficient) to G (least efficient).

operties are also given a score. The higher the number the lower your fuel bills are likely to be.

e average energy rating and score for a property in England and Wales are D (60).

## eakdown of property's energy performance

is section shows the energy performance for features of this property. The assessment does not consider the condition of a sture and how well it is working.

.ch feature is assessed as one of the following:

- very good (most efficient)
- good
- average